

Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 210	CHIPPINGHOUSE ROAD	Aesculus hippocastanum	Damage to Surface	Damaging	TR: Replanting, Betula ermanii - Plant in new 800 pit o/s 210 (same as felled tree)	434735.14	385247.69	Betula ermanii	434734.93	385247.7
o/s 185	CHIPPINGHOUSE ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800 pit o/s 185 (same as felled tree)	434798.53	385239.99	Liquidambar styraciflua 'Worpl	434798.38	385240.12
o/s 207	CHIPPINGHOUSE ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Betula ermanii - Plant in new 800 pit o/s 203 - relocated slightly away from 207 driveway	434685.14	385235.83	Betula ermanii	434688.82	385235.85
adj 27 (facing flats 221-227)	CHIPPINGHOUSE ROAD	Tilia x europea	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800 pit facing flats 221-227 (same as felled tree)	434582.93	385242.44	Tilia americana 'Redmond'	434582.91	385242.35
o/s 230 (opposite flat 217)	CHIPPINGHOUSE ROAD	Aesculus hippocastanum	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800 pit facing flats 217 (same as felled tree)	434596.49	385242.69	Tilia americana 'Redmond'	434596.25	385242.69
opposite 126-128	CHIPPINGHOUSE ROAD	Aesculus hippocastanum	Damage to Surface	Damaging	TR: Replanting, Liquidambar styraciflua - Plant in new 800 pit centrally opposite 126- 128 (same as felled tree)	434932.93	385222.01	Liquidambar styraciflua 'Worpl	434932.99	385222.51